## Milwaukee

## **SERVICE PARTS LIST**

## BULLETIN NO. 54-06-2365

SPECIFY CATALOG	REVISED BULLETIN	DATE			
CORD		June 2014			
		CTADTING		WIRING INSTR	UCTION
CATALOG NO.	2352-20	STARTING SERIAL NO.	G21A		

EXAMPLE:

Component Parts (Small #) Are Included When Ordering The Assembly (Large #).




FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.
1	14-38-2352	Lens / Screw Assembly	(1)
2		Lens Assembly	(1)
3		M3 x 8mm Pan Hd. T-10 Screw	(4)
4	12-20-2352	Service Nameplate	(1)

## FIG. NOTES

- 3 Care must be used when securing fasteners in tool. To prevent stripping do not over tighten. It is not recommended to use power tools, hand tighten only. Torque screws #4 to 5-7 in/lbs (6-8 kg/cm). Torque screws #10 to 3-4 in/lbs (3.5-4.5 kg/cm).
- A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or nameplate.