

#### **PowerPEX**<sup>™</sup>

### Bullet™

#### Spin Closed Stub Out

• Type L copper

#### **Bracketed Stub Out**

- Perfect for stubbing up through floor for closets or lavs
- Square O Strap is crimped to tube 8" from spin closed end on 638X212E
- Type L copper

#### Open Ended Stub Out

• Type L copper

Item No	Connection	CTS	Length	Pkg	Min Qty	Case Qty						
SPIN CLOSED												
638X208	½" F1807	1/2"	8"	В	100	100						
638X212	½" F1807	1/2"	12"	В	100	100						
638X312	3/4" F1807	3/4"	12"	В	50	50						
638X208PK	½" F1807	1/2"	8"	C*	20	20						
BRACKETED SPIN CLOSED												
638X212E	½" F1807	1/2"	12"	В	50	50						
OPEN												
643X208	½" F1807	1/2"	8"	В	100	100						
643X212	½" F1807	1/2"	12"	В	100	100						



# **PowerPEX**<sup>™</sup>


## Stub Air™

### Brazed Air Chamber Tee Fitting

- Eliminates on-the-job costs such as: measuring, cutting, cleaning, fluxing and soldering of up to four joints
- Sturdy brazed saddle joint cannot be damaged during field soldering and will not fracture due to jobsite abuse
- · Provides stub out and air chamber with PEX connection in one piece



682XL5240







#### Leakproof Spin closed ends have five times the wall thickness of the copper tube. Each fitting is factory inspected.

Item No	Connection	Type.	Branch		Air Chamber		. Pkg	Min	Case		
		1,00	CTS	Length	CTS	Length	8	Qty	Qty		
SPIN CLOSED											
682XL5240	½" F1807	L	1/2"	8"	1/2"	12"	В	25	25		
682XL5240PK	½" F1807	L	1/2"	8"	1/2"	12"	C*	10	10		
OPEN											
682XL5213	½" F1807	L	1/2"	1½"	1/2"	12"	В	25	25		

